Introduction

Shining 3D DentalScan EX+ User Manual V2.15

AutoScan series are specially designed to provide solution for dentistry with expertise, developed by Shining3D Tech Co. Ltd independently. The process of calibration and scan are fully automatic. Scanner brings precise 3D scanning and effective order management, providing the customers with a simple and intuitive workflow to improve the efficiency of production

The manual describes Scanner consisting of following parts

- 1. The Use of Fixture
- 2. Create Order
- 3. Scan Operate
- 4. Pre-design function
- 5. <u>Scan Type</u>
- 6. Occlusion
- 7. <u>Calibration</u>
- 8. System Test
- 9. <u>Notes</u>
- 10. <u>Safety Notices</u>
- 11. Contact Us



Copyrights & Legal

Shining 3D Tech Co., Ltd. All rights reserved. No part of this publication can be reproduced, transmitted, transcribed, or translated into any language in any form by any means without the permission of Shining 3D Tech Co., Ltd.

Disclaimer

This user manual is an instruction for installation, operation, and maintenance, but not product warranty. All efforts have been made to ensure the accuracy and completeness of the information in this manual. However, Shining3D Tech Co., Ltd. accepts no responsibility for any errors or an omission contained in the documentation and reserves the right to explain and revise the publishing and fault of this manual. The information in this manual is subject to change without notice.

Shining 3D Tech Co.Ltd.

1. The Use of Fixture

The fixtures will be used to fix model, models in occlusion and die(s), etc. The details of fixture are as follows.

^{1.} The fixture of Calibration plate

² www.shining3ddental.com

SHINING 3D"

- 2. Model fixing fixture
- 3. The fixture of die
- 4. <u>Height adapter</u>
- 5. Fixing of articulation transfer fixture
- 6. The fixture of dental model
- 7. Fixing targets fixture

Accessories

antity	Picture	Usage
1		To connect scanner and compu
1		To power ups
1		To provide power








	SHINING 3D"	AutoScan-DS User Manual	
1			To scan impression
1			For calibration, die(s) scanning and dental arch scanning. Placed directly or scanner's rotation base
1			For articulator scanning
1		2	Pad for dynamic articulator




1.1. The fixture of Calibration Plate



Calibrate plate

The fixture of calibration plate: align the No. 1 hole at the base of calibration plate with the No.2 hole on the rotating table.



1.2. Model fixing fixture



Front side

back side



Model fixture fixing: Align the No.1 hole on the fixture with the No.2 hole on the rotating table.



Fixture of DS-EX+:

(1)Following the direction of the red arrow, push the plaster model to the edge until it is fully inserted





(2)Take Amann Girrbach plaster model for example, it shall be fine when the transfer plate and the plaster model are overlapped at the circled area as below.




www.shining3ddental.com

1.3. The fixture of Die



clamping


(1) **The fixture of tooth die**: Align two arrows on the die tray and rotating table, as well as hole 1 and hole 2.



1.4. height adapter

height adapter: it can be applied in following processes(calibration, die scanning, upper jaw and lower jaw scanning of non-articulation transfer order)





Static articulator scan pad: use it during static bite scan. See Artex articulator below as an example:



www.shining3ddental.com

Place the articulator onto the scanner as below picture:





Front view

Bird's eye view

Dynamic articulator scan pad: it is used for dynamic articulator scan process, see Corident articulator below as an example:





AutoScan-DS User Manual




Place the articulator onto the scanner as below picture:





AutoScan-DS User Manual



ront view

15

Bird's eyes view

F

1.5. The fixture of dental model

(1) The fixture of dental full arch: Place full arch model on the plate, fixing by rubber band, blue-tack or screw depends on dental models and model fixing fixture came with the scanner, shown as the images below.





The model fixing fixture came with the scanner, shown as the images below.



(2) the fixture of the quadrant arch : Fix the quadrant jaw with blue-tack, shown as the figure below.





(3) The fixture of occlusion: Use rubber band or wax to fix upper arch and lower arch in occlusion, and fix them by using blue-tack or screw on the plate, please see images below





(4) Impression Fixture

4.1Fix the fixture

The impression fixing fixture came with the scanner, shown as the images below.




AutoScan-DS User Manual



(5) **Die Fixture**: insert the teeth into the hole of blue-tack.



(6) Inlay fixture: in order to scan the inlay completely, when make sure the groove line on the inserted inlay is in line with the straight line between hole 5 and hole 8.



(7) **Implant model fixture**: it includes fixing the teeth model with scan pole and fixing teeth model with gum.





Clamping tooth model with scan pole


- (8) waxup fixture
 - 8.1Partial arch






8.2Full arch





8.3Die with waxup



2. Create Order

www.shining3ddental.com

SHINING 3D"

AutoScan-DS User Manual

User have to calibrate the scanner before perform any scanning, otherwise message will pop-up.

To launch calibration, user could open DentalScan.exe software and click icon , or Click "Start "of Windows, locate DentalScan >Calibration.Please refer to chapter "Calibration" for more information.

AutoScan offers three methods to create new order, the scanning process is the same yet no matter how the order is created.

1.Create order from DentalManager.exe

2.Create order from exocad DentalDB

2.1. DentalManager

DentalManager is consist of two parts:1. Order Information 2. Settings



on desktop or

User could open DentalManager by clicking icon from "Start"of Windows> DentalScan >DentalManager

2.1.1. Order information

The order is divided into three modes according to different user requirements:Patient mode,Multidie mode,Clinic mode.

2.1.1.1. Patient mode

Select "patient mode" as shown in the picture below.

SHINING 3D

AutoScan-DS User Manual

Order Int	formation 3	Tooth 21
🗐 Date	2020-04-20 13:57:14	12 (11
0	037	(13)
 Order Number 	037	14 15 U
. Doctor	001 / Doctor001 🛛 🗸 🕂	16
Patient Code	037	17
□ Patient Name		18
.a. Technician	001 / Operator001 🛛 🗸 🕂	48 Clear
🕑 Notes	Shade:none;Special Requirements:none	47
		45
		(44)
		(43) (42)(41)

- ① Customer service: contact after-sales personnel & connect with support via TeamViewer
- ② Calibration: calibration software
- ③ Order Information: for user to edit order number and fill in information such as doctor, patient, technician, notes, etc.
- ④ Tooth Notation
- (5) Scan Type and Occlusion Type
- 6 Restoration

25

www.shining3ddental.com

Other information

2.1.1.2. Multidie Mode

Select "multidie mode" as shown in the picture below.

34	SHINING3D [®]	Dontal	Ordor	Suctor
1-0	SHIMINGSD	Dental	order	System

Information	New	Load Save 🗁 Explore	v 🕇 Upload 🕬 Design
Order List			
	Order Inf	ormation 3	Tooth 8
	Date	2020-04-20 14:06:32	
	ID ID	037	
	Order Number	037	
	🖳 Doctor	001 / Doctor001	
	Patient Code	037	6
	□ Patient Name		
	🔔 Technician	001 / Operator001 🛛 🗸 🕂	7
	🖄 Notes	Shade:none;Special Requirements:none	
			Clear
Setting			
About			
			5
 Custor 	mer service:	contact after-sales personnel &	e connect with

support via TeamViewer

- ② Calibration: calibration software
- ③ Order Information: for user to edit order number and fill in information such as doctor, patient, technician, notes, etc.
- ④ Die Plate
- ⑤ Restoration type

2.1.1.3. Clinic mode

Find "device type" under "Setting" button, select "clinic", click "Apply" button, then the following interfaces pop up, for separated/impression/Non separated model.

Separated model:

SHINING 3D"

AutoScan-DS User Manual

SHINING3D [®]	[®] Dental Order	System	
Information	New	Load Save 🗁 Explore 🛱 Preview	v 🕇 Upload 👓 Design
Order List			
	Order Inf	ormation 3	Tooth 12
	🖹 Date	2020-04-20 14:09:25	
	e ID	037	13
	 Order Number 	037	14
	🚊 Doctor	001 / Doctor001	16
	Patient Code	037	17
	□ Patient Name		18
	🚊 Technician	001 / Operator001 🛛 🗸 🕂	48
	🖄 Notes	Shade:none;Special Requirements:none	47
			(46) (45)
			44
			(43)
Setting			
About			Occlusion

- ① Customer service: contact after-sales personnel & connect with support via TeamViewer
- ② Calibration: calibration software
- ③ Order Information: for user to edit order number and fill in information such as doctor, patient, technician, notes, etc.
- ④ Tooth notation



- ⑤ Restoration type
- 6 Bite option
- ⑦ Materials and parameters

Impression

SHINING 3D"

AutoScan-DS User Manual

SHINING3	D® Dental Order System	
Information	New Coad Save 🗁 Explore 🔯 Preview	v 🕇 Upload 🕬 Design
Order List		
	Order Information	
	Date 2020-04-20 14:09:25	
	© ID 037	
	⊘ Order Number 037	
	Doctor 001 / Doctor001	
	Patient Code 037	
	□ Patient Name	
	A Technician 001 / Operator001	
	Notes Shade:none;Special Requirements:none	
		EDAN
Setting		Ortho 9
About		

- (8) Scan type: single arch impression, wax bite, plaster stone.
- ③ Orthodontic option: scan data can be integrated in design software if it is ticked.

Non-separated model



SHINING3D	[®] Dental Order	r System
Information	New	Load Bave Explore 🛱 Preview 🕇 Upload 🗪 Desig
Order List		
	Order Inf	ormation
	🗒 Date	2020-04-20 14:09:25
	ID ID	037
	 Order Number 	037
	🚊 Doctor	001 / Doctor001 V +
	Patient Code	037
	□ Patient Name	
	🚊 Technician	001 / Operator001 V +
	🖉 Notes	Shade:none;Special Requirements:none
Setting		
About		
a natami		

- ① natomy diagram
- 1 Free scan: jaws can be switched during process.

Notes :

How	to	check	tooth	definition:Right	click	on	tooth	and	select
31				www.shining3ddental.com					

restoration type.

How to copy a defined tooth information : Choose a defined tooth first, press Ctrl and click another tooth you want to apply the same settings

How to copy tooth information: Select tooth with set information and click new tooth.

Attention: click spare part of tooth notation will cancel the current information.

After user create a new order, fill order information, define teeth and click Save, the Scan button will be available, now user can perform scanning by clicking Scan.

2.1.2. Order data share

2.1.2.1. Private Cloud

Dental cloud aims to connect labs and clinics, which allows users to manage their information with parents.

Please go to http://dental.shining3d.com

2.1.2.2. Account registration

To register for the dental cloud account, click the "Register" link to go to the dental cloud website. It is recommended to open the dental cloud website using browsers such as Chrome, Firefox, and Safari.

igure account	
Mail login	Phone login
Please input mail ad	ldress
Please input passwo	ord
Register	Forget password

Click "Login" in the top right corner of the homepage to open the login page.



AutoScan-DS User Manual

Dirpit my parment	Sel up and manage connections to labs, hospitaliclinic, or user of doctor Vew and manage your cases Vew and manage your cases Vew and manage your institution when adaptive permession supplied Manage your Shamg3D Dental Cloud profile	
(Regel my parment	hospitalicine, or user of doctor • View and manage your cases • View and manage your institution when adaptive permission supplied	
Dirget my pairword	Wee and manage your institution when adaptive permission supplied	
	 Manage your Shining3D Dental Cloud profile 	
EMEA Region		
SHINING 3D Technology Carble		
TE1_+40-711-28444009		
Panorama, Heibronner straße 86, 70191, Stuttgart, Germany		
Support Email		
dental support@shining3d.com		
	SHINING 3D Technology GmbH TEL: +49-711-2044009 Paronama, Heitbonner straße 8 Support Email	

"Create new account", select the registration type.

♀ ♀I am a hospital/clinic: register as a hospital/clinic institution and administrator. After registration is successful, you need to wait for the system administrator to review before you can log in.

♀ ♀I am a doctor: register as an individual user. You can log in directly after registration.

♀ ♀I am a lab: register as a dental laboratory and administrators. After registration is successful, you need to wait for the system administrator to review before you can log in. Note that this type of account can only be used on the web side and cannot be used on the desktop client.

Fill in the real application information as required (the notification of information such as the relationship network and order status will be sent to the mobile phone number and email address filled in the application)



AutoScan-DS User Manual

- Name	Diespital					
* Addr.	740 César Chávez St. Unit D. San Francisco, CA 94124, United States					
Captcha	b V byd					
Set up a de	fault administrator account.					
* Contact	Doctorij	•				
* Mobile	us +1 United States • 2594787	۰				
* Email	al 2594787@qq.com					
* Password		•				
* Password		0				
again						
Privacy 📴	You must agree to our data protection policy and check it out. Please read it carefully:					
	Apply New					

After the registration is successful, the page automatically jumps to the login interface, enter the mailbox or mobile phone number and password, you can tick "Remember Password" for subsequent quick login.

mail Mobile	
29444089@qq.com	•
•••••	۰
Remember Password	1 forgot my password

After the login is successful, the hospital, clinic or doctor's account can establish a network connection with the partner technical institution (i.e. add a lab)

2.1.2.3. Networking

The network can only be created by a doctor/hospital/clinic account and then the lab can accept or reject the connection. The doctor can only upload the order data to the laboratories that accept the connection. After logging in as a hospital, clinic or doctor account, select "Relational Network" in the upper right corner of the interface to create a new network.

SHINING 3D"	AutoScan-DS U	Jser Manual
New	Connection	×
* Use	DoctorL[12345@qq.com][49 0	
* Lab	☑ 2	
	All 许严行技工所[lab]	Close Submit
curre au		

- ① User: Select the user
- ② Lab: Select a partner lab from the drop-down list
- ③ Submit: Submit the newly created network

The submission is successful and is displayed in the page list. The relationship status of the newly created relationship is "to be confirmed". You need to wait for the lab to accept the confirmation (the relationship status is "active"), and only after the relationship is confirmed by the lab can clinicians the data.

2.1.2.4. Institution management

Institution administrators can add / remove members for this organization.

After login, select "Admins" ->"Members", and create a new administrator and ordinary members for the institution.

		New Member	×
		Notes: Mobile or Email must supply one for password reset, announce, etc. Default password is 888888.	
		*Belongs Al 🗸 🕦	
		* Nick Name	
		Mobile 86 Call Maple	
		Email	
		is Admin 🔲 3	6
			Close Submit
1	Belor	ngs: Select the name of the institution.	
2	Nick	Name: Member nickname.	
35		www.shining3ddental.com	

③ Mobile: The mobile number of this member. It is also the account of the mobile phone user. The default password for login is 888888. You can either fill in the mobile phone or mailbox.

④ E-mail: This member's e-mail. It is also the account of the e-mail user. The default password for login is 888888.

⑤ Is Admin: Set the member as an administrator. The default is No.

6 Submit: Fill in the information and the member is added successfully.

Remove members:

Select the member to be deleted, select the "Delete" button, and confirm the deletion.

cases Management:

After login, select "Case" in the upper right corner of the page to list all cases managed by this member.

1.24	Destre	Palery	140	-	-	10 N		G Same	
0 m () m () m ()	No. bearing the state	Entropy 5 to	Carlot Carlot States	X	() minut	22 Carlos			1
ryan -	Perent	1.00	Nequirement			Status;		Armen	
() no for scalar da and da n formania no folk	84	600423H	Descript Space Separat Descript organization and Apartment From Antonyole Apartment From Antonyole Apartment (PADA), San Rowani, 110 Die 201 Juli Miller Separation	ingo tene		Banus Had Cord Copie by 2010-2 808) Update 45:2214 0 22082 Nami Cordon Had Brigging with 2010 40	un under Un under	7000	н
	-	maria	Design type receil (seeing experiment can warring PADM (2007) Tables (2007) Tables (2007)	antinee begintee bigstike		Balan Hal Cort Down by Drive Will Spran 1; Drive TANK Name Control Hal Dripping Will Data Bil	i niet nie 42 state 11 i i i i i tri 72 state 1	diamy.	8
	10	max18	Dengin type mpan Dengin mandromenti ang Ardagental Matemati Pitata, Jan Dengin Pita ta 2023 di sti Dengin mananani	the two in two i		Hadaq Hild Desig Design Fy 2016-2 Dynam Fy 2016-2 Dynam Fy 2016-0 Dynam Fy 2016-0 Dynam Fy 2016-0	a any the flat state.	Mariane Intelling	н

Doctors and technicians can communicate instantly on the web page, select \blacksquare to expand the communication box, transmitting information or documents.


SHINING 3D

AutoScan-DS User Manual

Issue Me	issage
Content	
Attach	Drop file here or
	Select File
Issue	

2.1.2.5. Order status

The order is transferred between the hospital (clinic/doctor) and the laboratories, and the two parties cooperate to advance the entire process from visit to completion of treatment. The doctor operates in the client Dental Manager Pro, and the lab operates on the web page side. The most common workflow for uploaded order is as follows:



Brief introduction to the workflow:


(1) Doctor uploads order data: see the previous section for details.

(2) The lab refused to accept the order: the technician of the lab refused to accept the order.

(3) The lab received the order: the technician of the lab can download or preview the order data.

Project Files		
File		
2019-11-19_001_009.zip	± Download	Preview
2019-11-19 07:48:03 [UTC] [finished]		

The lab confirmed the order.



(4) The design plan uploaded by the lab: the technician of the lab uploads the design plan, including the documents and data.

Upload	Design			
Are you s sunnyLat	ure to do action "Upload Design" for orde	er 5f20aab4-4546-58b9-b13c-661b5c	18dfc5f issued by doctor Doct	ort.) for patient Snow to La
lesign re faterials looths F0	/pe.repair quirement AnatomicInlay,Antagonist (COMP_3ax.2) 31 26:33 nie Special Requirements:none			
iotes				
Attach	Drop file here or			
	Select File			
Sr Sr	tow-Order Design png	1.1 MB	Success	
s s	now-Order Design docx	80 KB	success	

Select the file to be uploaded. After the file is uploaded successfully, click Submit.

(5) Doctor confirmed plan: After the technician uploads the design plan, the order status is "Need Confirm Design", and the doctor can download the design plan in the client Dental Order System.

Choose	download file	
⊘ Snow	-Order Design.png	\sim
		- i i

The design data is saved by default in the DesignData folder of the

order catalog. The doctor can approve the design plan by clicking "Confirm Design" and the order status will become "Making"; if not approved, the doctor can click "Request Re-design" and make clear the design requirements, and the order status will become "Accepcted", which requires the lab to redesign and upload the plan. Then the doctor can check the plan again.

Design requ	uirements	

the doctor chooses not to review the design when uploading data, skip this process.

(6) During the making of the lab: After the doctor confirms the design plan, the order status is "Making", indicating the processing data of the lab.

(7) Delivery by the lab: The data processing is completed in the lab, and the logistics information is submitted and the goods is delivered. The order status is "Delivering".

Shipping	2
We you sure to do action "Shipping" for order 5f20aab4-4546-5669-b13c-661b5d6dtc5f issued by doctor sunnyLab?	DoctorLi for patient Snow to Lab
Design Type repart Length Type repart Length Theorement Anatomicritisty Antagonest Materiana COAM - Jan 20 Dorber F107 8-3 Shade none Special Requirements none	
"Supplior	
YuanTong	۰
Shipping Num	

(8) Doctor confirmed the receipt: After the lab delivers the goods, the doctor can view the logistics information, and confirm the receipt after receiving the goods. The order status is "Finished". If the doctor does not receive the goods or the goods have problems, the doctor can request a re-delivery, and the order status is "Wait Shipping". In this circumstance, the lab needs to re-deliver the goods, and the doctor can

confirm the receipt after receiving the goods.

(9) Finished: This order is completed

2.1.3. Settings

User can check or configure settings by accessing Settings button.

SHINING3	D [®] Dental Order System		
Information	Setting		
Order List			
	Save EXO Order		Dental C
	Save 3rd Party Order	2	🔽 l have
	Save DentalWings Order	3	Connec
	User Interface Language	English V	
	Dental Notation	FDI World Dental Federation notatic V 6	
	Device Type	Clinic V 6	
	Scanner Software Path	DentalScan\DentalScan.exe Select Path	
	Dental Model Viewer Path	alViewer\DentalViewer.exe Select Path 8	
	EXO DentalCAD Path	Select Path 9	
	Dental Order Path	C:\DentalOrder1 Select Path	
	Order File Naming Rule	Order Number_Order ID Customization 1	
Setting			
About		A	oply

① If enable this option, exocad dentalDB can import the order directly, The default setting is active.

② If enable this option,3rd party software can import 3D data with preferred orientation.The default setting is inactive.

AutoScan-DS User Manual

③ Save DentalWings order: If enable this option,DentalWings software can import 3D data for design directly.Currently only support crown and bridge indications. The default setting is inactive.

④ User interface language: user can modify the interface language and default language is decided when users install the software.

⑤ Dental notation: FDI world dental federation notation and universal numbering system.

6 Device type: Clinic, DentalScan. The default is DentalScan.

 \bigcirc Scanner software path: users can set the software path.

8 Model preview software path: users can set the software path.

③ Configure order output directory.

0 Data Cloud: Public Cloud, Private Cloud_ The default is Private Cloud.

① Order file naming rule: users can name the order file folder with their own preference.

D DentalCloud : The privacy policy needs to be agreed. See the order data share(2.1.2) for configuration.

Note: To save and make setting change takes effect, please click 'Apply' button after configuration.


2.2. EXO

The activate tool are only used to bundle with Exocad, users don't have Exocad software don't need to bundle.

There are three steps: start activation tool, select bundle files and then bundle successfully.

① Start activation tool

After installation is finished, select start 'Activator' or choose



Click 'start activation tools'; see the photo as below, click button of 'select '

lease select Exo	executable file DentalDB.exe	
1		Select
	Start Bind	

Find the path for DentalDB.exe; choose DentalDB and then bundle with the software.

Organize 🔻 Ne					
-	w folder				1
 Quick access Desktop Downloads Documents Pictures 4GS cy Release_Denta SVN OneDrive This PC Network Khomegroup 	llScan	**	Name OpenSource.dll-LICENSES prerequisites ClearWPFFontCache.exe CopyAndOpen.exe OpentalDB.exe WorkParamConfigTool.exe	Date modified 10/20/2016 1:36 AM 11/12/2014 1:23 AM 10/20/2016 1:35 AM 10/20/2016 1:40 AM 10/20/2016 1:41 AM 10/20/2016 1:41 AM	Type File folder Application Application Application

③ Binding successful

Click 'start binding' to bundle with the Exocad, if it is successful, there will be a reminding show as below.

ase select Exo e	xecutable file DentalDB.exe	
E: \exocad-Dent 20 \DentalDB \bin	alCAD-win8-64bit-2014-02- \DentalDB.exe	Select
	Start Bind	



AutoScan-DS User Manual



3. Scan Operate

The following function buttons will be used during scanning, they can made the scanning process more convenient.



D	Scan Model		
	O Separated model	Non separat	ed model
2	Impression		
	Upper jaw		O Registered jaw
	Lower jaw		O Registered jaw
	Setting		
	Dental notation	FDI numbering system	~
	Create data for third party		
	🗹 Gingiva scan first		
	🗌 (Waxup/Gingiva)Auto Extract		
	AI scan		
	Post and core scan		
	All In One		
0	Articulator	OStatic	Dynamic
0	Articulator Transfer		
2	Articulator Type	AG	~
3	Scan Path Strategy	Normal	Advanced
4	Scan Data Strategy	Maximun Speed	O Best Quality
5	Do not show it again		ОК



Separated model	O Non separa	ated model
Impression		
Upper jaw	OImpression	O Registered jaw
Lower jaw		O Registered jaw
Setting		
Dental notation	FDI numbering system	~
Create data for third party		
Scan antagonist model first		
🗹 Gingiva scan first		
🗌 (Waxup/Gingiva)Auto Extract		
AI scan		
All In One		
Articulator	OStatic	Oynamic
Articulator Transfer		
Articulator Type	AG	~



Separated model	Non separated model
Impression	
Upper jaw	O Impression O Registered jaw
Lower jaw	O Impression O Registered jaw
Setting	
Dental notation	FDI numbering system
7 🗹 Texture 💿 obj	j Oply Oply (For Maestro 3D/iPD/Digilea)
8 TextureCorrect	
Create data for third party	
🗹 Gingiva scan first	
✓ Gingiva scan first (Waxup/Gingiva)Auto Extract	
UWaxup/Gingiva)Auto Extract	

hange between separate model and non-separate model scan mode.

sers can choose upper jaw and lower jaw to be impression or registered jaw(gypsum mod **on**:"FDI World Dental Federation notation"and "Universal numbering system"to choos

for third party: Once checked, software can export 3D data compatible with 3sha

nactive.

first: check this option to scan the gingiva first before scanbody or abutment.

a)Auto Extract: Once checked, waxup and gingiva data will automatically delete overl

ck this option to excute automatic intelligent add-scan after the completion of model **scan:** occurs at scan orders of inlay, which is also for post scan.

For scan orders of separated/unseparated models with indications of crown/coping/ve where the occlusion type is two stone.

Static mode, swing(dynamic scan) mode

ransfer: it occurs when tick Articulator, providing transferring function.

ype: occurs when tick articulator transfer, including AG, Bio-art, Kavo, SAM.

: When users scan unseparate model, they can choose normal or advanced mode; advanced er time but better scan result.


ategy: When users scan unseparated model/impression, they can choose speed priority o


gain: Once checked, pre-set window will not pop out next time. If needed, users can er.

st model first: Priority to scan antagonist model once tick this option.

e **calibration:** it's available once selected texture. Before that, better to calibra color. No need to calibrate white & black scanner.

re will automatically calibrate white balance once put the board on edge, until finis checked, software will capture texture.








Click "intelligent add-scan" to enter automatic add-scan




AutoScan-DS User Manual









indows: click the "auto adjust" button, the program will adjust the brightness based ically and this is benefit to scanning process.

: **adjustment:** users can drag the bar or click on the arrow buttons to adjust the Ze better view of the scan object.

preference: users can choose preferred data height to display by activating this func s a real-time display of scanning model during and after scanning process;

when the scanning process is done, users can cut and delete the unnecessary data; use king mouse key to adjust the cut height . SHINING 3D"

AutoScan-DS User Manual

can:If there is data remain unscanned on the model, you can rotate to the specified in " button to do the add scan.You can also use the shortcut keys (double-click the l keyboard) to trigger the manual add-scan operation.While entering the next interface, "Insert the model" and scan the model again if you want to add scan to the model.

the button "apply" when the scan process is completed, then software will registe nodel .and saved the STL in the "Scandata" folder; the button "Next"can also registe nodel

he latest mended data is not suitable, click this button to discard the latest mended dd-scan : if the scan data is incomplete, users can choose certain areas for add-scan -scan automatically starts by clicking "Scan"; different levels of intelligent You can use the shortcut keys (double-click the left mouse button or press the 1 on operation

gital model will rotate to a preset angle.

click the "+,-" button or move the slider or click the slider and roll mouse wheel t

advanced (12 scan positions), medium (9 scan positions), basic (6 scan positions) n:left click mouse to select hole filling areas; selected areas will turn red; u g both "shift"and left mouse key to choose; users can adjust the ball size by press d.

ntelligent add-scan.

om intelligent add-scan.

iew, top view, fit view.

intelligent add-scan process, users can click it to exit from add-scan and display d click Free Edit or Rect Edit and Brush Edit, press the "shift" key and press delete.

tion\cancel selection: reverse the selected region or clear the selected region.

e the selected region.

do the latest delete operation or redo the delete operation.

tment: optimization is performed when the Ti- base shoulder is thin

oof: optimize the problem of poor data caused by severe reflection on the abutment (

illing: at the final complete step, users can swipe open the function and manually mm in circumference; more options are provided for hole filling; click the kettle-li

SHINING 3D"	AutoScan-DS User Manual	
Radius: Fill Hole	fill three levels of radius 2/4/6 after the order was com	ıple
allow scan models with gingiva or relief wax, without power spray.		
an press left and right mo	ouse keys at the same time to move the data.	
	The state of the second s	


can rotate the data by right clicking the mouse key.

3.1.1. Range scan

.



Steps: put in the model, click button of 'Range Scan', press left mouse button to select the target area of model, and then click Scan to start range scanning.



Select target area

Scan result


Select the scanning area: press left mouse button to select the scanning area, users can select several areas for one model, the system will scan the chosen area.

Cancel select: cancel the selected area. Click the button of 'cancel select', the selected area will be canceled, users can reselect the scanning area or click '' to start scanning the whole model.

3.1.2. Manual alignment

Manual alignment is designed especially for the condition that the auto alignment of tooth and jaws fails. Take the tooth manual alignment for example. (the manual alignment of combination jaws is the same as that of tooth)

As shown in the figure below, the auto alignment of the tooth 35 and 37 fails.




Note: If you have checked the tooth number in the window "Align result view", then click "Manual Align", the tooth will not be displayed, you have to exit and enter again.

Click "Manual Align" to enter the alignment interface, the operation is as follows.

1) choose the tooth 35


Choose the tooth 37 to begin the manual alignment.

www.shining3ddental.com




2) click 3 groups of corresponding points

Operate according to the prompts to double click the corresponding tooth to select it, shown as the figure below. Double click 3 groups of points respectively on the tooth 35 and the model on the right.



3) click "Select"


After selecting the 3 groups of points, click "Select" to complete the alignment, the result is shown as the figure below.



4) choose the tooth 37


After completing the alignment of the tooth 35, you can click "Exit" to view the alignment result, or you can choose the tooth 35 to continue the alignment.

Choose the tooth 35, and the tooth 37 will be hidden, shown as the figure below.




5) click 3 groups of corresponding points

Operate according to the prompts to double click the corresponding tooth to select it, shown as the figure below. Double click 3 groups of points respectively on the tooth 37 and the model on the right.



6) click "Select"

After selecting the 4 groups of points, click "Select" to complete the alignment, the result is shown as the figure below.




7) Reset&Clear

Reset: users can click 'reset' to go back to the data before alignment if you are not satisfied with the result.

Clear: users can click 'clear' or click the right mouse button to clear the selected points if you are not satisfied with the selected position.






8) Exit

If the alignment result is right and satisfactory, click "Exit", it will display the alignment result, shown as the following figure.






Note:

- 1. You can cancel the selected points by right clicking the mouse.
- 2. After completing the alignment of the first tooth manually, if you click "Exit" or choose another tooth, the alignment of the first tooth will be saved and the "reset" is invalid.
- 3. When clicking the 4 groups of corresponding points, you'd better choose the area with obvious features. Please don't choose the points at the same plane.
- 4. When scan more than one teeth on the die, the alignment of a few teeth may fail, you need to align the teeth manually.
- 5. If the tooth for alignment is the existing model, or you go back to the last interface after auto alignment, it will result in failure in auto alignment. Then you need to align the tooth manually again.



4. Pre-design function

After finishing the scan, a series of pre-design functions will be displayed to the left side of the completion interface. The pre-design functions vary with different scanning process.



Manually fill holes: all the holes are identified, you can manually select the hole hem;

Mark tooth number : mark the tooth number information of the model ;

Extract margin line: draw and extract the margin;

Check undercut : display the undercut of the model ;


Seal the screw channel: seal the screw channel of the abutment in a digital way.

Modeling: perform operations of model shell, bottom sealing & lettering


4.1 Swap jaws

This function is only activated in the scanning cases of "Non-separated model - all in one" and "triple tray"

click button to activate this function.



Note : all the pre-design data will be deleted when using this function. After a successful swap :




4.2 Manually fill holes

This function is enabled for all scanning cases except"Texture scanning".

click button to activate this function.

www.shining3ddental.com





The holes in the model will be shown with green borders. Move the slider to adjust the radius for filling holes. Holes whose radius is smaller than set will be filled and displayed with red borders.


You can left click on the green border to fill the hole; or right click on the red border of the sealed hole to cancel the filling.

Click \bigcirc to cancel all previous filling. Click \checkmark to apply the current modification and close this function. Click \checkmark to cancel the current modification and close this function.

4.3 Mark tooth number

This function is enabled for all scanning cases. Die, abutment and scan body will be marked automatically.

If manual tooth marking is required, please click with to manually mark tooth.



www.shining3ddental.com




imesto cancel this modification and close this function.

4.4 Extract margin line

This function will be enabled on the completion interface of all the scanning cases. Tooth number marking is required before using this function.



📂 to activate this function.



www.shining3ddental.com

the current tooth as the visual center. Double click the left mouse button to generate a green point. By double clicking the point for four times, the margin line will be automatically generated.

If you are not satisfied with the automatically generated margin line, you can continue to double-click to add points, the new margin line will be adjusted along these additional points. You can also hold down the left mouse button and drag the points to adjust the margin line.

The point will turn to red after you left click it, which means the point is selected. At this time, you can click If the point is not selected before you click margin will be deleted.


Click \square or \square to switch between the teeth.

Click Sto apply current modification and close this function. Click stored to cancel current modification and close this function.


4.5 Check undercut

This function will be enabled on the completion interface of all the scanning cases. Tooth number marking is required before using this function.


Click to activate this function :



4.6 Seal the screw channel








If the tooth number has been marked, the model will be displayed with the current tooth as the visual center. Double click the left mouse button to generate a green point. By double clicking the point for four times, the sealing line will be automatically generated.

Click 🖉 to seal the screw channel. The sample is as follows:



Click 🦳 🔍 🔊 Lo switch between the abutments.
Click 🚺 to cancel previous sealing (Note: once only).
Click 📃 ≓ 🛛 to swap upper and lower jaw.
Click 🗹 to apply current modification and close this function. Click
💌 to cancel current modification and close this function.

4.7 Modeling

Modeling: This function is only available during impression scanning

SHINING 3D"


and non-separated model scanning.

		Q	×	¢
	10m			Ê
	191	20	TI	P
	RC			K
Adjust model height and choose post-processing nethod				
Ipper jaw model height. 23.869 mm				
Shell 3mm Bottom sealing				

Click to excute the operation of model shell, bottom sealing and lettering.

Drag the blue disk to adjust the height of the model, select the modeling method, click Shell and select the height of the shell from the





drop-down box. Then click Next. The shell is done.

Click Bottom sealing then click "next", bottom sealing is finished.



Click

Back to go back to the previous step.

Type content in the input box & double-click the model to display the lettering information, drag the font on the model to change its position A Magnify the font size Reduce the font size. The sample is as follows



				Ë	4	×	K
				B AN	Yor	and y	
•			4	yl	shinir	W	5
					SILL	igua	114 A.
	\otimes						
Enter text and double-click the imprinting shining3d	e model for text						
1871 	size: 3 A+ A-						
Back	Next						670
~		`		Q 🖶			
icking	will gopora	+]	ata madal a		مى مال	dalina	

Clicking will generate a complete model and exit the modeling function. Click to cancel the current modification and exit the modeling function.

5. Scan Type

The scan type contains "Separated model", "Non separated model", "Impression" and "Die".Following orders are all created through DntalManager.exe. The following examples of scan type are all based on the condition that the "Occlusion" type is "None".

Note:

1.After a model is scanned, you can "Add scan"and "Edit"it. If you go to the next interface and click "Back"to return, you will not be able to "add scan"to the model, but you can still edit it. If you need to add scan to this model, you must go back to the interface of "please insert the model"step to scan again.

2. Under the interface of "please insert the model"and click "Next", you can not "add scan" to the model if you use the existing model, but you can edit it.

3. When the number of crown and veneer is no more than 8, you can scan these models at a time. If the number is more than 8, you need to scan these models more than one time.

4. You can scan only one inlay each time. If there are several inlays in an order, you should scan several times correspondingly.

5.1.1. Separated Model

The "Separated Model" is designed especially for the separated model, which contains scan types as follows: single crown, inlay, veneer, wax crown, wax inlay, combination and so on.

You need to clamp the model during scanning, please refer the following links for the reference.

- 1. The clamping of crown: please refer to the clamping of a jaw
- 2. The clamping of tooth: please refer to Tooth clamping
- 3. The clamping of inlay: please refer to Inlay clamping
- 4. The clamping of implant: please refer to Implant clamping

5.1.1.1. Crown

(1) Create Order

You can choose "Single Crown" in the "Crown", then choose the tooth to be scanned (you can choose one or several teeth at a time) ; the "Scan type" is "Separated Model" and the "Occlusion" type is "None", shown as the figure below. SHINING 3D"




Information	New	Load Bave 🗁 Explore 🔯 Preview	v 🕇 Upload 🕬 Design
Order List 3rd-party	Order Info	rmation	Tooth 36
order list	🖹 Date	2020-06-10 15:52:08	12 11
	⊡ ID	1082	(13)
	 Order Number 	1082	14 15 12
	Doctor	001 / Doctor001 V +	16
	Patient Code	1082	(18) Clear A
	口 Patient Name		48 Ciear Cu
	🐣 Technician	001 / Operator001 🗸 🕂	47
	Notes	Shade:none;Special Requirements:none	(45) (45) (44) (43) (42)(41)(32)
			Scan marker for jaw mov
Setting			Scan Type Separa
About			Occlusion None

(2) Scan Jaw

After creating the order, click "Scan", the following interface will pop up. According to the tips on the interface, insert upper/lower jaw, and click "Next".



After automatic scanning, you can click "Add Scan" to have better scanning result if need be. Then you can click "Apply" for data optimization as below.




Note: After a model is scanned, you can "add scan"and "Edit"it. If you enter the next interface and click "Back"to return, you will not be able to "add scan" to the model, but you can still edit it.

(3) Scan Tooth

After scanning the jaw, click "Next", it will enter the scan interface, shown as the figure below. Then insert the tooth according to the tips.






Note: When the number of crown and veneer is no more than 8, you can scan these models at a time. If the number is more than 8, you need to scan these models more than one time.

After automatic scanning, you can click "Add Scan" to have better scanning result if need be. Then you can click "Apply" for data optimization as below.






Note: After the model is scanned, you can "add scan"and "Edit"it. If you enter the next interface and click "Back", you will can not "add scan"the model, but you can edit it only.

(4) Auto Alignment

After completing the die scan, click "Next"to enter the auto alignment interface, shown as the figure below.






Note : After the alignment fails, you can align the model manually.

(5) Completing scan

After the alignment is completed, click "Next", the interface will pop up, shown as the figure below. Click "complete", the whole order is completed.





Rotate the jaw to observe that there are parting line between the aligned tooth and jaw, shown as the figure below.

5.1.1.2. Inlay

(1) Create order

You can choose "Single inlay"in the "Inlay/Onlay", then choose the tooth to be scanned (26 and 27), the "Scan type"is "Separated model"and the "Occlusion" type is "None", shown as the figure below.


SHINING3D [®] Dental Order System					
Information	New	Load 💾 Save 🗁 Explore 🔯 Preview	v 🕇 Upload 🗪 Design		
Order List					
3rd-party	Order Info	rmation	Tooth 27		
order list	🗒 Date	2020-06-10 15:54:15	12 11 2		
	ID ID	1082	(13)		
	 Ørder Number 	1082	(14) (15) UPPEI		
	Doctor	001 / Doctor001 V +	16		
	Patient Code	1082	17 18 Clear A		
	□ Patient Name		48 Clear Curr		
	A Technician	001 / Operator001 🛛 🗸 🕂	47		
	🖄 Notes	Shade:none;Special Requirements:none	45 LOWEI		
		nequi ementa.none	(44) (43)		
			42 41 31		
			Scan marker for jaw move		
Setting			Scan Type Separat		
About			Occlusion		

(2) Scan Crown

The scan operation is the same with the "Single jaw" in the "Separated model", refer to the \underline{Crown} for the operation.

(3) Scan the first tooth

Insert the tooth "26, 27" into the die according to the prompts, then begin to scan, refer to $\underline{Scan Tooth}$.




(4) Auto alignment

After the scan of the tooth "26, 27" is completed, it will enter to auto alignment. Refer to <u>Auto Alignment</u> for operation.

(5) Completing scan

www.shining3ddental.com

After the alignment is completed, click "Next", the interface will pop up, shown as the figure below. Click "complete", the whole order is completed.



Note: You can scan only one inlay at each time. If there are several inlays in a order, you should scan several times.

5.1.1.3. Veneer

(1) Create order

www.shining3ddental.com

SHINING 3D"

 SHINING 3D"
 AutoScan-DS User Manual

 You can choose "Veneer" in the "Inlay/Onlay", then choose the tooth to be
 scanned , the "Scan type" is "Separated model" and the "Occlusion" type is "None", shown as the figure below.

SHINING3D[®] Dental Order System

Information	New	Load 💾 Save 🗁 Explore 🔯 Preview	w 🕇 Upload 🕬 Design
Order List			
3rd-party	Order Info	rmation	Tooth 21
order list	🗄 Date	2020-06-10 15:55:43	12 11 2
	ID ID	1082	(14)
	 Order Number 	1082	15 UPPE
	Doctor	001 / Doctor001 V +	(16)
	Patient [⊕] Code	1082	18 Clear A
	□ Patient Name		48 Clear Cur
	🐣 Technician	001 / Operator001 🛛 🗸 🕂	47
	🛛 Notes	Shade:none;Special Requirements:none	45 44 43
			42 41 31
			Scan marker for jaw move
Setting			Scan Type Separa
About			Occlusion None

Scan Crown (2)

The scan operation is the same with the "Single jaw"in the "Separated model", refer to the <u>Crown</u> for the operation.

5.1.1.4. Implant

There are four types of restoration for implant as follows implant
abutment
implant wax
abutment wax

Note:

During the implant scanning process, either upper jaw or lower jaw can be scanned with implant. If there are implant on both upper and lower jaws, it will lead to scanning and design error.

5.1.1.4.1. Implant


Implant includes 6 steps: Create order, Scan bridge wax,Scan gingiva, Scan scan bar, extract the implant bar, Complete.

(1) Create order

Choose "Implant" in the interface, then choose the tooth location of the implant, shown as the figure below. The "Scan type" is "Separated Model" and the "Occlusion" type is "None".

SHINING 3D"

AutoScan-DS User Manual



Note: the scan type of implant can only be "Separated model". It is set by default and can not be modified.

(2) Scan gingiva

SHINING 3D"


AutoScan-DS User Manual

After creating the order, click "Scan", the interface will pop up. Insert the up/lower jaw with gingiva (<u>Gingiva Clamping</u>)



After automatic scanning, you can click "Add Scan" to have better scanning result if need be. Then you can click "Apply" for data optimization as below.





(3) Scan bar of implant


After scanning the gingiva, click "Next"and enter the interface shown as the following figure. Then Insert lower jaw with scan body (<u>Bar</u> <u>Clamping</u>) according to the prompts.






After automatic scanning, you can click "Add Scan" to have better scanning result if need be. Then you can click "Apply" for data optimization as below.






(4) extract the implant bar

After scanning the Scan body, click "Next", it will enter "extract the implant bar" interface , then select tooth number and click corresponding implant bar. Thus the software will generate bounding volume automatically, shown as the figure below.



click "Next", it will enter the extract the implant bar finished interface, shown as the figure below.






(5) Completing scan


After the collect the implant bar is completed, click "Next", the window will pop up, shown as the figure below.





If you want to edit "Lower jaw"only, you can uncheck "Lower gingiva". Or else, you should uncheck "Lower jaw". If you check the two options, the two options will be edited simultaneously. After edit is completed, click "complete"to complete the whole order.





5.1.1.4.2. Abutment

Abutment scanning includes 5 steps: Create order,Scan Gingiva, Scan abutment, Scan die, Complete


1) Create order

Choose "Abutment"in the "Implant"area; then choose the tooth location(single or multi tooth); "Separated Model" for Scan type and "None" for Occlusion. See the following picture for reference.

SHINING 3D"

AutoScan-DS User Manual

SHINING3D[®] Dental Order System



2) Scan gingiva

Gingiva scanning is the same as implant's gingiva scanning, please refer to <u>Implant's gingiva scanning</u>


3) Scan abutment

Scan bar scanning is the same as implant's scan bar scanning, please refer to implant's scan bar scanning

4) Scan die 104 Die scanning is the same as crown's scanning, please refer to <u>Crown's tooth scanning and auto-alignment</u>

5) Complete

After scanning, click "Next" to enter the "Complete" interface. You can choose the model with the right column for edition



5.1.1.4.3. Implant wax

wax scanning includes 6 steps: Create order, Scan bridge wax,Scan gingiva, Scan scan bar, extract the implant bar, Complete.


There is "Bridge wax"added.

1) Create order

Choose "Implant wax" from "Implant"area; then choose tooth location(single or multi tooth); "Separated Model" for Scan type and



"None" for Occlusion.See the following picture for reference.



2) Scan bridge wax


Please refer to single bridge wax's Scan wax crown

3) Scan gingiva

Please refer to implant's scan gingiva

- 4) Scan scan bar
 Please refer to implant's scan scan bar
- 5) Collect the implant bar
- 6) Please refer to implant's extract the implant bar
- 7) Complete


You can choose the model with the right column for edition



If you don't want to edit the lower jaw bridge wax, you can uncheck it, same for other options. After edition, click "Complete" to finish scanning.



AutoScan-DS User Manual



5.1.1.4.4. Scan abutment wax

Abutment wax scan includes 6 steps: Create order, Scan gingiva, Scan abutment, Scan die, Scan bridge wax, Complete.


There is "Bridge wax"added.

1) Create order

Choose "Implant wax" from "Implant"area; then choose tooth location(single or multi tooth); "Separated Model" for Scan type and "None" for Occlusion. See the following picture for reference.

SHINING 3D"

AutoScan-DS User Manual



2) Scan bridge wax

Please refer to single bridge wax's Scan wax crown

3) Scan gingiva

Please refer to implant's scan gingiva

4) Scan abutment

Please refer to implant's scan scan bar


5) Scan die

109

Please refer to crown's tooth scan and auto-alignment

6) Complete


You can choose the model with the right column for edition



If you don't want to edit the lower jaw bridge wax, you can uncheck it, same for other options. After edition, click "Complete" to finish scanning.



AutoScan-DS User Manual



5.1.1.5. missing tooth (Pontic)

You can refer to "Scan combination" for the operation of scanning missing tooth.

Note:

the missing tooth can not be scanned alone, it should be scanned with crown, inlay or veneer together. The missing tooth is not an individual, and it can be ignored.

5.1.1.6. wax


wax contains many scan types. The main types are as follows.

wax Crown

www.shining3ddental.com



You need to insert the following models during scanning.



Part of the model


Whole jaw

5.1.1.6.1. wax Crown

(1) Create order

Choose "Pontic Wax" in the interface, then choose the tooth location(37 and 35), choose the "missing tooth wax", then choose the tooth(36), shown as the figure below. The "Scan type" is "Separated model" and the "Occlusion" type is "None".


SHINING 3D"



(1) Scan wax crown


insert the partial lower crown model with wax, click "Next"to begin to scan.





After automatic scanning, you can click "Add Scan" to have better scanning result if need be. Then you can click "Apply" for data optimization as below.





(2) Scan crown

After creating order, click "Scan" to enter the following interface. Insert the lower crown according to the prompts, refer to the <u>Crown</u> for the operation.






(3) Scan tooth

After scanning the crown, click "Next", it will enter the scan interface, shown as the figure below. Insert the model according to the prompts, refer to <u>the Scan Tooth</u> for the operation.






(4) Auto alignment

After scanning the tooth, click "Next", it will enter the auto alignment interface, shown as the figure below.






Note: it displays the alignment result between tooth and crown in the interface, the wax is not displayed in the interface.

(5) Completing scan

After the alignment is completed, click "Next", the interface will pop up, shown as the figure below. You can view or edit the model, click 118 www.shining3ddental.com SHINING 3D"

"Complete" to save the model.



Note: you can design the wax after editing the data in the interface.

5.1.1.7. Scan combination

There can be different types of teeth in a order, you can operate according to the selected scan type and tooth type. If scan a order of single jaw, a inlay, veneer and missing tooth, the steps are as the follows.



Choose the tooth type of a pontic (the tooth 15 and 17, the missing tooth 16), the tooth 24 and two inlay (26 and 27) in the crown, shown as the figure below. The "Scan type"is "Separated model" and the "Occlusion" type is "None".

SHINING3I	D [®] Dental Order S	ystem	
Information	New [Load 💾 Save 🗁 Explore 🔯 Previe	w 🕇 Upload 🛛 exo Desig
Order List			
3rd-party	Order Information		Tooth 36
order list	🖹 Date	2020-06-10 16:12:35	12 (11)
		1082	13
	 Order Number 	1082	(14) (15) UP
	A Doctor	001 / Doctor001	(16)
	Patient ⊡ Code	1082	
	口 Patient Name		48 Clear of
	🐣 Technician	001 / Operator001 🛛 🗸 🕂	47
	Notes	Shade:none;Special Requirements:none	40 (45 (44) (43) (42)(41)
			Scan marker for jaw m
Setting			Scan Type Se
About			Occlusion

Note: the missing tooth can not be scanned alone, and generally it's scanned with the crown.


(2) Scan crown

After creating order, click "next" to enter the interface of scanning crown. The scan operation is the same with the "Single jaw"in the "Separated model", refer to the <u>Single Crown</u> for the operation.

(3) Scan tooth

After scanning the crown, click "Next", it will enter the interface of scanning tooth, shown as the figure below. Scan the die at first. After scanning the die, it will enter the auto alignment interface. Refer to <u>"Scan tooth" and "Auto alignment"</u>.






Note:

- 1) After scanning the tooth on the die tray, it will enter the interface of auto alignment.
- 2) when scan the teeth of inlay, crown and veneer at a time. When the number of crown and veneer is no more than 8, you can scan these model all at a time. If the number is more than 8, you should scan these model more than once.
- 3) Pontic tooth will not be scanned like the die.

(4) Completing scan

After the alignment is completed, click "Next", the interface will pop up, shown as the figure below. You can edit the model in the interface. After editing the model, click "Complete" to save the model.



5.1.2. Non separated Model

The"Non separated model" is designed specially for scanning jaw in the Non separated model, which contains single crown, inlay and veneer.

You need to clamp the model during scanning, please refer to <u>the</u> <u>clamping of a jaw</u> or <u>the fixture of the half jaw</u>

1. If there are different types of teeth or more than one tooth in an order under the "Non separated model", you need to scan it once only.

2. the missing tooth can not be scanned alone.


5.1.2.1. Single Crown

1. Create order

Choose the scan type of "Non separated model" and the "Occlusion" type is "None". Choose "Crown" in the "Crown", then choose the tooth location (one or more disjunct teeth), shown as the figure below.

SHINING 3D"


AutoScan-DS User Manual



2. Scan crown


After creating order, click "Scan", the interface will pop up, shown as the figure below. Insert the jaw according to the prompts.





Then click "Next" to begin to scan. After the models is scanned, it will align the scanned model automatically. When alignment is completed, it will show "Complete model optimization" at the bottom, shown as the following figure.






3. Complete scan

After the alignment is completed, click "Next", the interface will pop up, shown as the figure below. Click "Complete" to complete the scan,





Note: If there are different types of teeth or more than one tooth in an order under the "Non separated model", you need to scan it once only.

5.1.2.2. Single Inlay

The scan operation is the same with the "Single Crown"in the "Non separated Model", refer to the <u>Single Crown</u> for the operation.

5.1.2.3. Scan Veneer

The scan operation is the same with the "Single Crown"in the "Non separated model", refer to the <u>Single Crown</u> for the operation.

5.1.3. Impression

The "Impression" is designed specially for Impression models.

You need to clamp the model during scanning, please refer to Impression Fixture

Crown

The scan operation is the same with the "Single Crown"in the "Non separated model", refer to the <u>Single Crown</u> for the operation.

Note: If there are different types of teeth or more than one tooth in an order under the "Non separated model", you need to scan it once only.

5.1.4. Die

The "Die" is designed specially for a large number of simple tooth models. It is used to scan data for making the inner crown generally. Take the single crown as the example.

You need to clamp the model during scanning, please refer to the <u>Clamping of tooth Die</u>.


Single Crown

(1) Create order

Choose the scan type of "Die" and the "Occlusion" type is "None". Choose "Crown"in the "Crown", then choose the location of the tooth to be scanned (one or more teeth), shown as the figure below.

SHINING 3D"


AutoScan-DS User Manual




(2) Scan die

After creating order, click "Scan", the interface will pop up, shown as the figure below. Insert the die tray with teeth according to the prompts.






Make sure that die tray are inserted with die before you click "Next" to start scanning. After scanning, you can "Add scan"to get better scan result. Then click "Apply"to optimize the scan data as below.



(3) Completing scan

After the alignment is completed, click "Next", the interface will pop up, shown as the figure below. Click "Complete" to complete the order scan.





Note:

- 1. If there are three types of teeth in an order, which are crown, inlay and veneer, you can scan crown , Inlay and veneer at a time.
- 2. Scanning for die of upper and lower jaw are the same. When the number of crown and veneer is no more than 8, you can scan these models all at a time. If the number is more than 8, you should scan these models more than once according to the hole location on the die tray.
- 3. The scan type of die cannot be wax or implant and the "Occlusion" type can only be "None".
- 4. The missing tooth can not be scanned alone. When choose the missing tooth in the order, the type will be ignored by default.



6. Occlusion

None: The operation of None "Occlusion" type is introduced in <u>Separated</u> <u>Model</u>, <u>Non separated Model</u>, <u>Impression</u>, <u>Die</u>.

The following orders are created through DentalScan.exe.In this chapter, the "Registered jaw" and "Bite impression" will be introduced.

6.1.1. Registered jaw

Choose the scan process of "Registered jaw" according to the selected tooth type and scan type. Take the single crown in the "Separated model" for example .


Note: While scanning the combination jaws with wax, the wax can exist only in the upper jaw or lower jaw. If both of the two crowns have wax, the scan design will be wrong.

1) Create order

Choose"Non Separated model"for the scan type and"Two stone models occlusion"for"Occlusion" type. Choose "Crown"option in the "Crown", then choose the location of the tooth to be scanned (26, 48), shown as the figure below.

SHINING 3D"

AutoScan-DS User Manual



2) Scan the combination jaws


Insert the model according to the prompt, shown as the figure below, click "Next" to begin to scan.





After scanning the model ,the result is shown as the figure below.





3) Scan the lower jaw

After scanning the totaljaw, click "Next" to enter the interface of scanning the combination jaws.Insert the lower jaw according to the prompt.






4) Scan upper jaw

After scanning the Up jaw, click "Next" to enter the interface of scanning the combination jaws. Insert the lower jaw according to the prompt.






(5) Auto alignment

Auto alignment of the lower jaw


After scanning the totaljaw、loweraw、upperjaw model, click "Next" to enter the interface for auto alignment of lower jaw. It will align the model automatically. When alignment is completed, the model is shown as



Auto alignment of upper jaw

Click "Next" to enter the auto alignment of upper jaw (you can also choose the "Manual Align"), shown as the figure below.






(6) Completing scan

After the alignment is completed, click "Next", the following interface will pop up, shown as the figure below.





Note:

1. In the mode of "Registered jaw", if the selected teeth are all in the lower jaw, please scan the lower jaw first before scanning the upper jaw.

2. While scanning the combination jaws with wax, if there is a pontic in the upper or lower jaw, operate it according to the operation of the pontic with wax.

3. While scanning the combination jaws with wax, the wax can exist only in the upper crown or lower crown. If the wax exists in both of the two crowns, the scan design will be wrong. 4. If you click "Back" during the combination jaws scanning, the auto alignment will fail, and then you need to align it manually.

5. If you use the previous model by importing order, the auto alignment will fail, and then you need to align it manually.

6.1.2. Bite impression

According to the selected tooth type or scan type then choose the scan process of "Bite impression".


The order which includes wax model or the order which both up and down jaws had chosen teeth is unsupported to the "Bite impression" type. Take the single crown in the "Separated model" for example

1) Create order

Choose "Separated model" for the scan type and "Bite impression" for "Occlusion" type. Choose "Crown" option in the "Crown", then choose the location of the tooth to be scanned (26), shown as the figure below.

SHINING 3D"

AutoScan-DS User Manual



2) Scan the mushbite

Insert the model according to the prompt, shown as the figure below, click "Next" to begin to scan.



Please insert the upper jaw with the mushbite



3) Scan the jaw

After scanning the mushbite click "Next" to enter the interface of scanning the jaw. Insert the lower jaw according to the prompt, the detailed process can referred to "Non separated Model".



Please insert upper jaw



4) Completing scan

After the scan process is complete, click "Next" to the "complete" interface, the mushbite will align with the jaw automatically. After the alignment is completed, edit and delete the unneeded region to make the later design more easily.




AutoScan-DS User Manual

6.2. Triple Tray

Choose "impression" when users want to scan triple tray impression
1) Create order

Choose "impression" in scan type, choose "triple tray"in occlusion, choose "anatomic crown" in crowns/copings session as below.



2) Scan lower impression

After order is created, click scan to start scanning, insert the lower 147 www.shining3ddental.com



impression as requested.



3) Scan upper impression

After lower impression scan is finished, go to next step to scan upper impression.






4) Automatic alignment

Automatic alignment between upper and lower impression.

After both upper and lower impressions are scanned, go to next step to align two impression data.






5) Complete scan

After alignment is finished, go to next step to complete scan process.





7. Calibration

calibration precision directly affects the scanning accuracy of system. The system requires calibration under the following conditions :

- 1) 3DScanner is used for the first time or it hasn't been used for a long time.
- 2) 3DScanner suffered from serious vibration during transportation.
- 3) The scanned data is very rough surface, or problems appear such as


151

registration error.

Operation steps:


can open "DentalManager" and click You ... to activate calibration. It can also be activated by clicking 'DentalScan->Calibration' from the 'start' menu. When the following interface is displayed, you can select the corresponding calibration plate from the drop-down box. If there is no corresponding plate in the drop-down box, click "serial number of calibration plate not found?".

Select calibration plane



As shown below: type the serial number of the calibration plate you are using in the input box. After the download is done, click ok.






Click "Yes", the work table will rotate automatically. In addition, it shows "Scan Data" at the bottom, which means that it is collecting and calibrating. The whole process is running automatically. The interface is shown as the figure below.



AutoScan-DS User Manual

237 236 236 217 216 216 216 216 216 216 216 216 216 216 216 216 216 216 216 216 216 217 215 216 216 217 216 216 217 216 217 216 217 216 216 217 216 217 216 217 217 216 217 217 216 217 217 216 217 217 216 217 217 217 216 217 2	••• 227 ••• 218

It will take 7-10 minutes to complete the calibration process. $_{\circ}$ Once the calibration is completed, the calibration result will appear, shown as the figure below. It is the errors on X, Y, Z axis. Click "Finish" and the whole calibration process will be finished.



8. System Test

"SysTest" is used to observe the working condition of hardware and diagnose problem. Click the menu "SysTest", a dialogue will pop up, shown as the figure below. The interface contains the parts of ①camera control, ② projector control and ③turntable control.



SHINING 3D[°] System test

	•••••	
	e e • • • • • • • • •	• • • • • •
		• • • • • •
		* * * * * *
		• • • • • •
		• • • • •
Camera Control	CalibrateSt	Turntable Control
1.0.5	2:4:0	PCB version:
Left Camera CameraID: PGR 14071136	Right Camera CameraID: PGR14071139	X-
	Exp. Time 16.826 Toom In	<u> </u>
		Y-
Exp. Time 16.826 Zoom In		
Gain 11	Gain - 11 ×	X: 75
		X: 75 Y: 30
Gain — 11 📮		

The parameters of projector control and camera control are predefined before delivery, which is not suggested to reset. Technician checks the scanner working condition and make problem diagnosis by those setting.

As shown in the figure above, when adjust the parameters of turntable control, Click or to increase or decrease the value of the rotary angle on X axis, or to increase or decrease the value of the rotary angle on Y axis.

Note:

156

The parameters of projector setting and camera setting are predefined before delivery . To avoid abnormal working condition, it is not suggested to change the setting without technician advice. If the parameters are changed by users and then the scanner can not work properly, the users should adjust the parameters according to the following chapter: "<u>Guide</u> <u>for machine testing</u>" or connect with professional technician for help.

8.1.1. Guide for machine testing

User guide includes two parts: **Scanning process** and **Calibration process**. Please set the parameters according to the following operation guide

Notes:

- When the result of scanning or calibration is failed, we can test the scanner by setting "camera setting" and " turntable control" parameters
- + When doing calibration and scanning, there is no need to change.

1) Calibration process

Check the brightness and SetCalibrationOrg before calibration.

Choose for calibration and put the calibration board on the turntable. Adjust and to modify the exposure(set the proportion of red points to white points is about 1:5)

Put the calibration board on the turntable, click to reset. Input angle values in boxes. Click Y+,Y or X+,X- for adjustment, making sure that the calibration board is facing upfront and cross is projected on the middle of the calibration board as shown below. You can see the adjusted angle values of X and Y axes through. After the two calibration boards at the two windows are in the same position, click (SetCalibrationOrg) to complete the calibration initial point setting.



		• • • •
		••••
		•••(@)
		• • • •
	• • • • • • • • • • •	• • •
	• • • • • • • • • • • •	
• • • • • • • • • • • • • • • • • • • •		0.0
• • • • • • • • • • • • • • • • • • •	• • • • • • • • • • •	
••••••••••		
Camera Control	 ◎ CalibrateSt	Turntable Conti PCB versio
Left Camera CameraID: PGR 14071136	Right Camera CameraID: PGR14071139	X-
Exp. Time 16.826 Zoom In	Exp. Time 16.826 - Zoom In	(Y-
Gain - 9	Gain - 9 A	(7) ^{X: 75}
✓ Lock Right Exchange Came	ra	Y: 30
Projector Control	Cross	SetCalibrati

2) Scanning process


Please check exposure and SetMendscanOrg before first scanning.

Choose for scanning and input the dental model onto the turntable. Adjust to modify the model brightness(take the snapshot below for reference)

Put the dental model on the turntable, click to reset. Input angle values in boxes. Click Y+,Y or X+,X- for adjustment, making sure that dental model is facing upfront and the cross's horizontal line come across

the middle of the hole as shown below(circled in blue).


You can see the adjusted angle values of X and Y axes through . After the two calibration boards at the two windows are in the same position, click (SetMendscanOrg) to complete the mend scan initial point setting.







System test(AUTOSCANEPSA-AJ016A26)



9. Notes

- Don't insert the USB data cable and softdog into the USB ports in the same area.
- 2) Please use the Nvidia graphics card to acquire high efficiency

for scan.

- 3) Each software binds to a certain calibration plate; so don't mix up the calibration plates Number.
- 4) Please don't move the devices.
- 5) Please keep the scan box clean.

6) Please do not start the software in the U disk directly. You must copy the software from the U disk to the PC before using, and you must have

the permissions to read/write the folder of the scan software, or else the software will not work normally.

- 7) If the software reminds "cannot recognize the scanner" please turn off the scanner and shutdown the software, then unplug USB data cable that connect the scanner and PC, then plug back in.
- 8) Users can not insert the USB wireless card.

10. Safety Notices

- 1) Maintain good ventilation, keep environment temperature no higher than 30 $^{\circ}$ C, no flammable and corrosive materials in the air.
- 2) Carry and place it carefully, no crushing, prepare protection from sun, rain, vibration, etc.
- 3) Once machine malfunctions, dismantling and repairing are allowed only by professional personnel or under their guidance.
- 4) Watch your hand.
- 5) Children are forbidden to operate this machine.
- 6) Once machine lifetime comes to an end, please hand it over to authorized agency to deal with it, do not randomly throw away to dustbins.



11. Contact Us

Shining 3D Tech Co. Ltd

Add: No.1398, Xiang Bin Road, WenYan Street, XiaoShan, HangZhou, China

Email: dental_support@shining3d.com

Web: <u>www.shining3ddental.com</u>